

October 07, 2025

STRUCTURAL CERTIFICATION

Subject: IMS Academy Building
Location: Dorm 2, Paseo Saturnino, Barangay Banilad, Cebu City

This is to certify that Engr. Vendell Atillo, conducted an ocular site inspection and assessment of the IMS Academy building during the aftermath of the recent Bogo City fault line that occurred last September 30, 2025 with the corresponding earthquake magnitude of 6.7 intensity that was reported on the news by PhilVocs.

Based on the ocular inspection and evaluation of the building, it was found out that the building is generally in good physical condition and with no signs of structural damages, distress and settlements. Therefore, it is hereby certified that the said building is structurally stable, functional and fit for continuous occupancy.

The structural design of the said building was built accordance with the conforming provisions of the National Structural Code of the Philippines (NSCP) 2010 and 2015 Editions.



Engr. Vendell Atillo
Civil Engineer

PRC No. 0156940
Issued at Cebu City
Valid until 11/27/2026